



The 1st International Conference on

#### Masterbatch and Compound

15,16February 2016 - Iran Polymer and Petrochemical Institute

# New Generation of **Purging Compounds**

**Presenter:** Morteza Fathollahi

Paper Code: imbpa15-00150031



- Why Purging Compound
- Purging Options
- How ULTRA PURGE works
- Applications
- Productivity & Cost Analysis
- Training & Technical Services



## Why Purging Compound?

- How long does it take to complete a color/material change over?
- What's your plastic scrap rate?
- What does downtime really cost?
- Can you afford to lose a customer due to the quality failure?



## Why Purging Compound?



## When to purge

## Color Changes

### Carbon Removal

## Material Changes

Start ups Shut downs



## Vs in-house recycle resin

### **In-house Recycle Resin**

#### Replacing

Pre-conditioning might be required

**Process condition adjustment** 

Huge amount of material is needed

Low heat resistant in long time

### **Purging Compound**

Purging

**Ready to use** 

No change in process condition


Small quantity is enough (few Kg)

Suitable for Shut down / Start up




## **Commercial Purging Compounds**







## **Purging Options**






## What is ULTRA PURGE?

- Ultra Purge is a Chemical or Hybrid Purging Compound in a ready-to-use or concentrated pellet form
- It is designed to clean screws, barrels, shooting pots and hot runners when changing color or removing carbon contaminations.





## How ULTRA PURGE Works



\* Scrubbing Mineral introduced by ULTRA-X technology not in all grades; ULTRA-X technology is **100% non-abrasive** 



#### **Processes:**

- Injection Molding (Specially Hot Runners equipped)
- Blow Molding
- Cast & Blown Film Extrusion
- Fibers & Filaments
- Other Extrusions (Compounding, Pipe, etc.)

### **Polymers:**

- HDPE, LDPE, LLDPE
- > PP, TPO
- PVC, EVA, TPE, TPR, TPU
- ➢ HIPS, GPPS, ABS, SAN

- PET, PBT
- PA, PC, PMMA, POM
- ➢ PPS, PPO, PSU, PEEK



Two significant costs are generated when purging:

- Scrap: Amount of resin and purging compound used to clean the machine
- Downtime: Amount of time used to purge/clean the machine. This is inclusive of:
  - Lost of Production
  - > Energy used to run the machine while purging
  - Man power



- Scrap is normally the smallest component of the purging cost but it is definitely the most visible.
- Many companies monitor this as an indicator of efficient production.
- Reducing scrap during a color change can only be achieved by using a purging compound.








## Downtime

- Downtime is normally largest component of the purging cost when analyzing the purging process.
- Fast purging means gaining production up time as well as reducing the cost of energy and manpower.
- Purging compound are designed to reduce downtime making color and material changes faster.







#### Case 1- Door Panel; Color change from Black to Beige base on PP

Process	Inj. Molding	
Machine Size (Ton)	900	
Shot Size (gr)	453	
Cycle Time (s)	375	
Mold Type	Hot Runner	
Cavities	2	
Barrel Capacity (Kg)	4.5	1

	Item	Unit	Without Ultra Purge	With Ultra Purge
	Used Virgin Resin	Kg	45	6.4
	Price of Virgin Resin	Rls/Kg	42000	42000
•	Used Ultra Purge	Kg	0	1.4
	Price of Ultra Purge	Rls/Kg	380000	380000
	Total Material Cost	Rls	1890000	800800
	Time Required for Purging	min	30	15
	Downtime Cost	Rls/min	20000	20000
	Total Downtime cost	Rls	600000	300000
	Total Cost per Purging	Rls	2490000	1100800

Color Change Time per Week	2
Macine Sets	16
Saved Cost per Purging (Rls)	1389200
Annually Total Saved (million Rls)	2312



Scrap Cost Reduction %	58
Downtime Cost Reduction %	50

#### Case 2- Bottle Preform; Color change from Amber to Natural base on PET

Process	Inj. Molding	
Machine Size (Ton)	300	
Mold Type	Hot Runner	



Item	Unit	Without Ultra Purge	With Ultra Purge
Used Virgin Resin	Kg	128	27
Price of Virgin Resin	Rls/Kg	30000	30000
Used Ultra Purge	Kg	0	3.2
Price of Ultra Purge	Rls/Kg	600000	600000
Total Material Cost	Rls	3840000	2730000
Time Required for Purging	min	200	60
Downtime Cost	Rls/min	25000	25000
Total Downtime cost	Rls	5000000	1500000
Total Cost per Purging	Rls	8840000	4230000

Color Change Time per Week	1	
Macine Sets	8	
Saved Cost per Purging (Rls)	4610000	
Annually Total Saved (million Rls)	1918	




Scrap Cost Reduction %	29
Downtime Cost Reduction %	70

### Case 3- Car Part; Color change from Black to Grey base on PP, Ultra Purge vs other commercial purging compound

			Item	Unit	With other Purging	With Ultra Purge
		-	Used Virgin Resin	Kg	20	10
Process	Inj. Molding		Price of Virgin Resin	Rls/Kg	68000	68000
Tachine Size (Ton) 3000		Used Ultra Purge	Kg	24	11	
(>	5000		Price of Ultra Purge	Rls/Kg	200000	380000
			Total Material Cost	Rls	6160000	4860000
			Time Required for Purging	min	30	14
			Downtime Cost	Rls/min	21000	21000
			Total Downtime cost	Rls	630000	294000
			Total Cost per Purging	Rls	6790000	5154000

Color Change Time per Week	2
Macine Sets	2
Saved Cost per Purging (Rls)	1636000
Annually Total Saved (million Rls)	340



Scrap Cost Reduction %	21	
Downtime Cost Reduction %	53	

#### Case 4- Bottle cap; Color change from Red to White base on HDPE

Process	Inj. Molding
Mold Type	Hot Runner
Machine Size (Ton)	300



Item	Unit	Without Ultra Purge	With Ultra Purge
Used Virgin Resin	Kg	125	25
Price of Virgin Resin	Rls/Kg	39000	39000
Used Ultra Purge	Kg	0	7
Price of Ultra Purge	Rls/Kg	380000	380000
Total Material Cost	Rls	4875000	3635000
Time Required for Purging	min	240	60
Downtime Cost	Rls/min	20000	20000
Total Downtime cost	Rls	4800000	1200000
Total Cost per Purging	Rls	9675000	4835000

Color Change Time per Week	3	
Macine Sets	5	
Saved Cost per Purging (Rls)	4840000	
Annually Total Saved (million Rls)	3775	



Scrap Cost Reduction %	25
Downtime Cost Reduction %	75



### Using Ultra Purge:

- will reduce the rejects due to black specks and color streaking.
- will eliminate 100% of all remnants of color and resin that can potentially generate black specks or color streaking during production.
- will remove carbon deposits generated from thermo-sensitive resins.





## **ULTRA PURGE Benefits**

- Very efficient & productive in purging process
- Wide range of grades for different processes & polymers
- Easy to be removed from the machine
- Food contact certified by EU and FDA regulation
- 100% safe; All ingredients are GRAS from the FDA
- Ready & easy to use
- Odorless; It does not produce dangerous gases
- Available in Pooya Polymer Tehran warehouse
- Technical service by Pooya Polymer Tehran technical team



## **Correct Purging Procedure**

On-site training to help the operators deal with the purging task:

- When to use ULTRA PURGE
- Which ULTRA PURGE
- How much ULTRA PURGE
- How to use ULTRA PURGE
- When NOT to use ULTRA PURGE



## ULTRA PURGE Grades

GRADES TEM		S TEMPERATURE RANGE	DESIGNED FOR	DESCRIPTION		
	T min °C	T max °C	T min °F	T max °F		
HIGH-E™	190	320	374	608	ABS, PA, PS (crystal), GPPS, HIPS, PC, PMMA, SAN, PBT, PET	
LOW-E™	140	260	284	500	PVC, EVA, TPE, POM, TPR, TPU	
РЕТ-Е™	190	320	374	608	PET	Ready-to-use chemical purging
₽-О™	170	300	338	572	PP, PE, HDPE, LDPE, LLDPE, HIPS, GPPS, TPO	compounds
РС™	220	340	428	664	ANY RESINS GOING TO PC	
РММА™	200	280	392	536	ANY RESINS GOING TO PMMA OR PA12	
5150™	160	350	320	662	All resins within temperature range	Ready-to-use hybrid purging
5160™	190	320	374	608	ABS, PA, PS (crystal), GPPS, HIPS, PC, PMMA, SAN, PBT, PET	compounds with uItra-X™ technology
НТ™	200	380	392	716	PEEK, PPS, PPO, ULTEM, GRIVORY HT	Ready-to-use
ME-C™	190	350	374	662	All resins within temperature range	hybrid purging compounds
HT+™	250	400	482	752	PPS, PPO, PEEK, PSU, ULTEM	compounds
9010™	140	320	284	608	TPR, TPE, PVC, EVA, POM, PS, ABS, PA, PC, PBT, PPO, PMMA, PET	
9015™	140	300	284	572	PP, PE, HDPE, LDPE, LLDPE, HIPS, GPPS, TPO	Concentrate
Вр™	170	380	338	716	PP, PE, HDPE, LDPE, LLDPE, HIPS, GPPS, TPO	chemical purging compounds
РЕТ-С™	190	320	374	608	PET	compounds
РО-С™	170	320	338	608	PP, PE, HDPE, LDPE, LLDPE, HIPS, GPPS, TPO	



## A laminated custom made procedures alongside with scoops or buckets for easy dosage are provided.

## Easy, Ready, Quick & Error-free

#### CareFusion

#### Procedimiento Rápido ULTRAPURG Invección

#### Montener el berril lleno de la resina de producción (p.e. PP)

- 2. Aumentar las temperaturas de boquilla y hot-runners (Manifold y Tips), 100 "F (SE°C) 3. Carpar el ULTRAPURGE en la tolva (Ver tabla de cantidades)
- 4. Con el Molde Abierto (Canada cale activa de la moltades) estado en la molde abierto (Canada cale activa con la unidad de Invección reparada (Calada directa).-realice tiros contos hasta que ULTRAFUNGE sea visibia a tuviós de los het-runners y/o de la boquilla (EL ULTRAFUNGE se verá Se verá de color blanco y especipos).
- S. Ajuste la calor blance y or esperioso.
   S. Ajuste la calor blance al 10% del máximo permitido por el equipo y restince 3 tims cortos a través de las válvulas de compuerta con el molde alterno, as a través de las paguíla.
- abierto, o a través de la boquilla. 6. Deje reposar el material por 3 min. y cargue la siguiente resina de producción inmediatamente después de ULTRA PURGE.
- 7. Continue haciendo tiros cortos con ULTRA PURGE.
- 8. Haga 4 o 5 tiros mas con la resina de producción para completar la purga ajuste parámetros de la máquina para producción.
- 9. Si la contaminación persiste repita los pasos del 3 al 8. Nota: "Por pres presentados de velación, senti el territ de correctivado y segue los resentantes. Para al an
- <sup>4</sup> No molitary priori and CDMP/CDMP in a close of graduation a finite measurement. <sup>4</sup> No molitary priori and CDMP/CDMP grade Statis or molitaria graduation program. <sup>4</sup> Synchronization and CDMP/CDMP grade statistic and providence of a measurement of the integration.

For live technical assistance cell (714) 376-4978 • www.ultrapurge.com

#### Ultra Purge Quick Steps

#### 1. <u>Keep the barrel full of the previous production resin</u> (i.e. ABS)

- 2. Increase temps of the nozzle/hot runners (tips and manifold) 100° F
- Add Ultra Purge (See chart below for quantity). The amount to use should be roughly 1 barrel capacity.
- Mold parts until you see Ultra Purge show up in the molded part. If only
  purging the screw & barrel move carriage back and purge through nozzle.
- 5. With mold open...reduce the shot size to 10% of the maximum allowed shot size and make 2 short shots through the gates with mold open (i.e. if the max shot size is 100 mm then reduce the shot size to 10 mm). Make sure Ultra Purge is flowing through all the gates.
- Allow for a 5 minute soak after filling the hot runners and barrel with Ultra Purge. Add the next production resin directly after the Ultra Purge
- 7. Continue making short shots with the Ultra Purge (mold open)
- 8. Make 4-5 shots of the next resin to complete the purge...bring temps back down to production settings
- 9. If contamination persist repeat steps

Intellit: "For shuddowns... empty the barrel of Ultro Purge and turn off heater bands. Start up with half barrel capacity of Ultra Purge and begin production." "Do not moli duart out of Ultra Purge 5050/5060 on a mirror collahed tool

	Quantity of UI	tra	Purge Needed	
Press Number	Pounds Needed		Press Number	Pounds Needeo
30	5	1	52	9
31	4	1	53	18
43	13	1	54	24
44	4	1	55	21
51	9	1	58	46





## **Examples of Application**


#### Closures



#### **Automotive Parts**



#### Caps



#### **Medical Application**



#### **Hot runners**



### PVC Degradation Removal





## THANK YOU

#### Morteza Fathollahi

Business Development Manager POOYA POLYMER TEHRAN mobile: +98 912 2959 312 email: m.fathollahi@pooyapolymertehran.com